

## Reference List - DOW (2020-2025)

Updated: 06/2025

Plant/Site	Product Line	Smart Ram	PAP P2	PAP CPI	PAP ACHE	Test Plugs	Isolation Plugs
Bristol (PA)	HX Repair	X		X			
Deer Park (TX)	HX Repair Test & Iso		X	X		X	X
Dow Silicones (MI)	HX Repair			X			
Hahnville (LA)	HX Repair		X	X			
Iberica (Spain)							
Louisville (KY)	HX Repair	X	X	X			
Map Ta Phut Styrene Monomer (Thailand)	HX Repair			X			
Nederland (Netherlands)	HX Repair			X			
Oyster Creek (TX)	HX Repair		X	X			
Plaguemine (LA)	Test & Iso					X	X
Seadrift (TX)	HX Repair Test & Iso	X	X	X		X	X
St. Charles Taft Petrochemicals (LA)	Test & Iso					X	
Texas City (TX)	HX Repair			X			
Victoria (TX)	HX Repair		X	X			

**North, Central & South America EST Group** 2701 Township Line Road Hatfield, PA 19440-1770 USA | +1.215.721.1100 +1.800.355.7044 | est-info@curtisswright.com

**Europe / Middle East / Africa EST Group B.V.** Hoorn 312D 2404 HL Alphen aan den Rijn The Netherlands | +31.172.418841 | est-emea@curtisswright.com

**China** +86.400.636.5077 | est-china@curtisswright.cn | **Singapore** +65.3158.5052 | est-asia@curtisswright.com